Page 1 of 2

		Stackup			
Name	Material	Thickness	Lower Level	Roughness	
0	copper	0mm	0mm	0um	
ANTENNA	copper	0mm	0mm	0um	
		Layers			
Pattern		Name	Type		
		0	signal		
		ANTENNA	signal		
		Measures	•	measures	
		SIwave Regions	Slwave H	SIwave HFSS regions	
		Rats	rat		
		Errors		error	
		Symbols	symbol		
		Postprocessing		Postprocessing	
		Outline			