Controlling Variables

Pooja Patel

February 22, 2017

Variable Control		
Production Stage		Variables
Material Proper-		k (spring constant)
ties		
		c (thermal constant of the polymer used to create actuator)
		ρ (resistivity of the polymer used to create the actuator)
		LCL (length contraction factor)
		$\Delta \mathrm{T}$
Manufacturing	Inputs	loriginal (string length)
Process		
		N (number of coil turns)
	Outputs	L (length of actuator)
		A (Area based on diameter)
Operation	Inputs	T (temperature of actuator)
		V (Voltage)
		I (Current)
		R (resistance)
	Outputs	d (movement of actuator; displacement)
		P (Power)
		T (Temperature of actuator)