Government College Of Engineering, Amravati.

(An Autonomous Institute Of Government of Maharashtra) **Mechanical Engineering Department**

CT-2 (Winter2018) MEU-501 Machine Design-I MARKS-15 TIME-1 HOUR: 12pm to 1 pm Date-24/09/2018

Q.1 Attempt any two:

a) Define endurance limit. State the factors to be considered while Designing Machine parts to avoid 05 Marks fatigue failure.

b) Explain Gerber line and Soderberg line for combination of stresses.

05 Marks

05 Marks

c) Define stress concentration. State the different ways for reducing stress Concentration 05 Marks with sketches.

Q.2. A bracket as shown in fig.1, supports a load of 30KN. Determine the size of bolts, if the maximum allowable tensile stress in the bolt material is 60 MPa. The distances are L1 =80mm,

L2 = 250 mm and L = 500 mm

