	r=0 mm	r=10 mm	r=20 mm	r=30 mm	r=40 mm	r=50 mm	r=60 mm	r=70 mm	r=80 mm	$r{=}90~\mathrm{mm}$
X	0.000	-0.116 -0.118	-0.462 -0.472	-1.036 -1.057	-1.834 -1.870	-2.853 -2.904	-4.087 -4.150	-5.533 -5.600	-7.189 -7.247	-9.059 -9.089
У	0.000	-0.116	-0.472	-1.007	-1.070	-2.904	-4.100	-5.000	-1.241	-9.009