Ruiz, Patrick

From: Nguyen, Loan

Sent: Friday, May 3, 2024 7:23 PM

To: 5mm Lap Top Level; RSM-DMP1 Supervisors; RSM-DMP1 Energy; DMP1 Packaging; DMP1 White Boxing

Cc: QC-Clean Rooms

Subject: S/O 1519739 EB 215 Assembly Inspection Completed.

Hi Team,

S/O 1519739 EB 215 has been completed for Assembly Inspection. Please see the detailed Inspection report below.

Completed Device Assembly Inspection Report			
Model:	EB215		
Shop Order:	1519739		

Devices Inspected by QC	1902
Total Passed by QC	1872
Total Failed by QC	30
Total Failed by PRD	0

Non-Conformances -	Quantity 🚚	Scrap %		
Visual Inspection	3	0.16%		
Verify Insulation	13	0.68%		
Jaw Short	1	0.05%		
Continuity Range	6	0.32%		
Blade Activation	5	0.26% 0.05%		
Low Jaw Force	1			
High Jaw Force	1	0.05%		

"Visual Inspection" Details 🔻	Quantity ~		
Scratched	2		
Exposed wire sheath	1		

"Verify Insulation" Details 🔻	Quantity -	
Incorrect Insulation Orientation	3	
Insulation Damage	10	

All failed devices will be scraped per Q-40118864 Rev. R

Statistics for Shop Order #1519739

Device SN = 1902 Program Count = 1908

Program Success = 1901 Verification Success = 1872

CER Evaluation = 0 Lost Serial Number = 0

verification succes

Back	Device SN	PC Name	Program Count	Program Success	Date Programmed	Verification Success	CER Evaluation	Lost Serial Number
	6043240501193914			Undf.	2 May 2024 17:05:00	Success		

Thank you, Loan