

# Soldadura fuerte tubo de cobre

## Listado material

Tapa Cu 5/8"	2 ud.
Tubo Cu 5/8"	0,35 m
Racor 5/8"	2 ud.
Machón 5/8"	1 ud
Válvula soldar	1 ud




Tapa Cu 5/8"

TF 02 404

Tubo Cu ø5/8"

l= 5 cm


Ensanche



Tubo Cu ø5/8"  
L = 5 cm


Abocardado

Racor latón 5/8"



Machón ø5/8"

Abocardado



Tubo Cu ø5/8"  
L = 5 cm

Ensanche



Tubo Cu ø5/8"  
L = 5 cm

Ensanche



Tubo Cu ø5/8"  
L = 5 cm


Válvula soldar plana



1/4" SAE

TF 06 004

Ensanche



Tubo Cu ø5/8"  
L = 5 cm



Tapa Cu 5/8"

TF 02 404