

Soldadura fuerte tubo de cobre

Listado material

Tapa Cu 5/8"	2 ud.
Tubo Cu 5/8"	0,35 m
Tubo 1/4"	0,2 m
Tuerca 5/8" SAE	2 ud.
Unión SAE macho 5/8"	1 ud
Válvula soldar	1 ud

Tapa Cu 5/8"


TF 02 404

Tubo Cu \varnothing 5/8"

$l = 5$ cm

Ensanche

Tuerca latón
5/8" SAE
TF 03 074



Tubo Cu \varnothing 5/8"
 $L = 5$ cm

Abocardado

Unión SAE macho
 \varnothing 5/8"
TF 03 094

Abocardado

Tubo Cu \varnothing 5/8"
 $L = 5$ cm

Tubo Cu \varnothing 1/4"
 $L = 10$ cm
Conexión
manómetro

Tubo Cu \varnothing 1/4"
 $L = 10$ cm
Llenado presión N₂
o aire comprimido a
10 bar.

Ensanche

Tubo Cu \varnothing 5/8"
 $L = 5$ cm
Ensanche



Tubo Cu \varnothing 5/8"
 $L = 5$ cm

Ensanche

Tubo Cu \varnothing 5/8"
 $L = 5$ cm



Tapa Cu 5/8"
TF 02 404

Válvula soldar plana
1/4" SAE
TF 06 004