

Soldadura fuerte tubo de cobre

Listado material


Tapa Cu 5/8"	2 ud.
Tubo Cu 5/8"	0,35 m
Tubo 1/4"	0,2 m
Racor 5/8"	2 ud.
Machón 5/8"	1 ud
Válvula soldar	1 ud

Tubo Cu $\varnothing 1/4''$
 L = 10 cm
 Llenado presión N₂
 o aire comprimido a
 10 bar.

Válvula soldar plana
 1/4" SAE
 TF 06 004

Ensanche

Racor latón 5/8"
 TF 03 074



Ensanche

Tubo Cu $\varnothing 5/8''$
 L = 5 cm
 Ensanche



Ensanche

Tubo Cu $\varnothing 5/8''$
 L = 5 cm

Tubo Cu $\varnothing 1/4''$
 L = 10 cm
 Conexión
 manómetro



Tubo Cu $\varnothing 5/8''$
 L = 5 cm



Tapa Cu 5/8"
 TF 02 404