Gmail Paul Taylor <paulroberttaylor@gmail.com>

Re: Plot 34 Albany Wood Defects

1 message

Paul Taylor <paulroberttaylor@gmail.com> 17 January 2024 at 12:53
To: Lynn Carrington <Lynn.Carrington@crestnicholson.com>
Cc: Indy Dhaliwal <Indy.Dhaliwal@crestnicholson.com>, Albany Wood <AlbanyWood@crestnicholson.com>, Mark Collins <Mark.Collins@crestnicholson.com>, Customer Service SO <CustomerServiceSO@crestnicholson.com>, Jade Taylor <jade.millington@hotmail.co.uk>

Good afternoon,

Issue 4: This was present before we had even used the dishwasher - please confirm that this door will be replaced, not repaired

Issue 13: This is not settlement, the drylining is bulging. Regarding the patching, the entire wall needs to be repainted, and this was reported to Mark on the 11th October 2023.

Issue 22: The same needs to be rectified in the main bathroom

Issue 41, this was supposed to have been done already, as it was confirmed by Natalie Haigh on 5th October 2023 that the gutters had all been cleared. This was not true.

Issue 44: It is not acceptable to pay £1500 for grass for it to be ruined because of the DPC work, then have more turf just laid on top of the old dead turf. What is going to be done about this?

Issue 45: I was told that this is acceptable. It is not, because it doesn't need to happen. The driveway paving is higher there than it should be, hence the water ingress. It is not present on the other side because the paving is where it should be.

Not present on the issues list:

- Garage DPC. I am still waiting to be told where in the NHBC technical standards 100mm is acceptable. I was told by Eileen Guihen that the NHBC has signed this section off. I would like a copy of that sign off please.

- Main bedroom carpet to en-suite is not fitted correctly

- Master bedroom ceiling not even

- Dent in the wall in the en]suite toilet

- Mastic throughout is poorly done

- Glosswork in multiple places poorly done

- Main bedroom ceiling

- The paint on the floors from the original list of issues has not been done, and there are other areas where this is present. Please could you add this to the list.

- Granite worktop - bad scratch and there is what appears to be adhesive on some areas.

- The fridge door creaks badly when opened or closed.

- The blown tape on the kitchen ceiling, reported to Mark several weeks ago, has not been done. There is now another on the ceiling close to the kitchen patio door.

- The floors in several rooms upstairs creak badly when walked on.

- Left of kitchen sink - long dent in the plaster

- Join in stone worktop has worsened

- Kitchen patio door not open and closing easily or without creaking

Please could you contact the after care company to advise of the items not on the list they have. Please advise what on the list they will be addressing. Once we know what will be done I can confirm the date I can be available. Regardless of whether one or two days are needed, it would need to be a Tuesday and/or Wednesday.

More worryingly, there is now a very large crack in the render (almost the entire height of the wall) on the utility room side of the house. I need to know what will be done about this, how, and when. A house a few doors down had scaffolding up for render so this isn't an isolated incident. Photos attached. I will address this in a separate email also, as this is urgent with the weather we have been having.

Many thanks,
Mr Taylor

On Tue, 16 Jan 2024 at 11:42, Lynn Carrington <Lynn.Carrington@crestnicholson.com> wrote:

> Good morning, Mr and Mrs Taylor
>
> Hope all is good with you all.
>
> We have a company called Solent Aftercare who would like to attend Monday 22nd January or Tuesday 23rd January. They will repair many of the items on your 14-day inspection list. It may take them a couple of days at the very most.
>
> Wardrobe company Amari will contact direct to attend and adjust wardrobes.
>
> Munster have ordered the glass Paine and once delivered they will fit and fix the folded seals in other windows.
>
> Roman showers have ordered both shower enclosures and will contact directly with a convenient day to fit.
>
> Hope above is to your satisfaction.
>
> **Kind regards**
>
> **Lynn Carrington**
>
> **Sales Executive**
>
> Crest Nicholson South
>
> Curbridge Meadows, 7 Coldland Road Whiteley Fareham PO15 7QR
>
> T: 01489 232217
>
> www.crestnicholson.com/developments/curbridge-meadows/

Classified as General

WE ARE PROUD SIGNATORIES OF THE BUSINESS AMBITION FOR 1.5°C AND RACE TO ZERO.

WE LOOK FORWARD TO COLLABORATING WITH OUR STAKEHOLDERS TO DELIVER STRONG ACTION TO MITIGATE OUR SHARED CLIMATE IMPACT.

Crest Nicholson uses personal data about its customers, subcontractors, suppliers and for recruitment purposes in relation to the operation of its business in accordance with its Privacy Policy which can be found here. You can unsubscribe from our marketing communications by following the unsubscribe instruction within the communication itself or simply by contacting us. We may monitor email traffic data and content for the purposes of security and staff training. E-mail is not a secure means of communication.
The contents of this email are confidential to the addressee. Unauthorised access and use is prohibited. Any opinions expressed in this email are those of the individual and not of the Crest Nicholson group, unless specifically stated otherwise.

Crest Nicholson PLC is registered in England under number 1040616; registered office 500 Dashwood Lang Road, Bourne Business Park, Addlestone, Surrey, KT15 2HJ. Crest Nicholson Chiltern, Crest Nicholson East Anglia, Crest Nicholson Eastern, Crest Nicholson Midlands, Crest Nicholson South, Crest Nicholson South West, Crest Nicholson Yorkshire, Crest Nicholson Partnerships & Strategic Land are operating divisions of Crest Nicholson Operations Limited registered in England under number 1168311, registered office as above. www.crestnicholson.com.

2 attachments

20240114_160024.jpg
2170K

20240114_160016.jpg
2690K