Hw 3

2) The instruction outside of the branch and after it.

3) Program Counter

8) False

11) False

14) 20,000 times

15) negative

18) 4 byte

19) True

21) 2 locations of Stack pointer

22) 3 locations of Stack pointer

25) $0800 - $3FFF

Ch 4

3) 8 pins

10) The DDRx command makes a port an input or output.

17) You can access individual bits of a port without altering the rest of the bits on a port.

18) the zero bit thats high.