CS F342

Computer Architecture

Semester 1 – 2023 – 24 **Lab Sheet 8**

Goals for the Lab:

To know exception mechanism in MIPS


Be able to write a simple exception handler for MIPS machine

Background:

The relevant registers for the exception handling, in coprocessor 0

<u>Register Name</u>	<u>Usage</u>	
BadVAddr	(Bad Virtual Address) Memory address where exception occurred	
Status	Interrupt mask, enable bits, and status when exception occurred	
Cause	Type of exception and pending interrupt bits	
EPC	Address of instruction that caused exception	

Question: Why do we need EPC? Why can't we use RA?




Status Register:

- The user mode bit is 0 if the processor is running in kernel mode and 1 if it isrunning in user mode.
- The exception level bit is normally 0, but is set to 1 after an exception occurs. When this bit is 1, interrupts are disabled and the EPC is not updated if another

exception occurs. This bit prevents an exception handler from being disturbed by an interrupt or exception, but it should be reset when the handler finishes.

If the interrupt enable bit is 1, interrupts are allowed. If it is 0, they are disabled.

The Cause Register:



The branch delay bit is 1 if the last exception occurred in an instruction executed in the delay slot of a branch.

The interrupt pending bits become 1 when an interrupt is raised at a givenhardware or software level.

The exception code register describes the cause of an exception through the following codes:

Code	Name	Description
0	INT	Interrupt
4	ADDRL	Load from an illegal address
5	ADDRS	Store to an illegal address
6	IBUS	Bus error on instruction fetch
7	DBUS	Bus error on data reference
8	SYSCALL	syscall instruction executed
9	BKPT	break instruction executed
10	RI	Reserved instruction
12	OVF	Arithmetic overflow

a. Codes from 1 to 3 are reserved for virtual memory, (TLB exceptions), 11 is used to indicate that a particular coprocessor is missing, and codes above 12 are used for floating point exceptions or are reserved.

Exercise 1:

"https://sourceforge.net/p/spimsimulator/code/HEAD/tree/Tests/tt.core.s" HYPERLINK

"https://sourceforge.net/p/spimsimulator/code/HEAD/tree/Tests/tt.core.s"t.core.s

- Load it in QtSpim, ignore any compilation warnings, Click on Run
- Whenever exception pop-up appears, observe the values of registers used for exception handling and console message (also understand the corresponding piece of code used for causing that exception), then click 'OK'.

Exercise 2: Set branch delay bit as '1' by causing an exception in the delay slot of branch.

Note: Simulator => Settings => MIPS tab => check 'Enabledelayed Branches' then run the code

Exercise 3: Study the code below to understand exception handling mechanism in MIPS (Non-evaluative)

Exceptions and interrupts cause a MIPS processor to jump to a piece of code, at address 80000180hex(in the kernel, not user address space), called an exception handler. This code examines the exception's cause and jumps to an appropriate point in the operating system which then responds to it accordingly.

The code in the example below is a simple exception handler, which invokes a routine to print a message at each exception (but not interrupts). This code is similar to the exception handler (exceptions.s) used by the SPIM simulator.

.ktext 0x80000180

mtc0 \$k0, \$14 # *EPC*

#The exception handler cannot store the old values from \$at,\$a0,\$a1) registers on the stack, as would an#ordinary routine, because the cause of the exception might have been a memory reference that used a #bad value (such as 0) in the stack pointer.

```
mov $k1, $at # Save $at register. $k1,$k2 are exception handler register
```

```
sw $a0, save0 # Handler is not re-entrant(i.e interrupts are disabled) and can't use sw $a1, save1 # stack to save $a0, $a1 # Don't need to save $k0/$k1
```

#the exception handler uses the value from the Cause register to test if the exception was caused by an #interrupt (see the preceding table). If so, the exception is ignored. If the exception was not an interrupt, #the#handler calls print_excp to print a message.

```
mfc0 $k0, $13 # Move Cause into $k0, $13 is CAUSE register srl $a0, $k0, 2 # Extract ExcCode field(bits 2-6 in cause register) andi $a0, $a0, 0xf bgtz $a0, done # Branch if ExcCode is int (0) mov $a0, $k0 # Move Cause into $a0 mfc0 $a1, $14 # Move EPC into $a1 jal print_excp # Print exception error message done: mfc0 $k0, $14 # Bump EPC addiu $k0, $k0, 4 # Do not re-execute faulting instruction
```

```
mtc0 $0, $13 # Clear Cause register

mfc0 $k0, $12 # Fix Status register

andi $k0, 0xfffd # Clear EXL bit which allows subsequent exceptions to change the EPC register

ori $k0, 0x1 # Enable interrupts

mtc0 $k0, $12

lw $a0, save0 # Restore registers

lw $a1, save1

mov $at, $k1

eret # exception return, Return to EPC

.kdata

save0: .word 0

save1: .word 0
```

Exercise 4: Identify the cause of exception from the following values of CAUSEregister

- 1. 0x24
- **2.** 0x30
- 3. 0x1c