

Page 1 of 3

REPORT

CUSTOMER'S REF NO.:

ALS THAILAND REF NO.: ATT/ELP/14/4395-G
OUR REF NO.: ATS/ELT/0278/15
DATE: 01 April 2015

COMPANY: NMB-Minebea Thai Ltd.

1 Moo 7, Phaholyothin Road, Km.51 Tambon Chiang Rak Noi, Amphur Bang Pa in Ayutthaya Province 13180, Thailand

DATE SAMPLE RECEIVED: 19 March 2015 DATE ANALYZED: 25 March 2015 DATE TEST COMPLETED: 30 March 2015

SAMPLE DESCRIPTION: One lot of sample was received with references:

Description: MBA Lightning Bug3D (ww#32) date code 4325

Serial no.: 1YNZY, 1YL14 Lot QA: LN2A520007

Model: Lightning Bug 3D

Surface Area: Hub: 9.25 cm2, Base: 115.49 cm2

METHOD/PROCEDURE:

Analysis	Procedure No	Sample Size	Extraction Medium	Extraction Vol (ml)
GCMS	D0000180658	1 piece	n-Hexane	Motor Hub 10 mL,
Extractable	Rev.K		(HPLC grade)	Motor Base 60 mL

RESULTS:

The Specification is based on Seagate's Doc 20800010-160 Rev.BE for Spindle Motor / Motor Base Assembly (2.5")

Motor Oil Contamination	Maximum Allowable Amount (ng/cm2)	Results (ng/cm2)
Motor Oil - Base	0.6	0.14
Motor Oil - Hub	10	Not Detected
Motor Hub	Maximum Allowable Amount (ng/part)	Results (ng/part)
Repeated Hydrocarbon (C20-C40 Alkanes)	NA	Not Detected
	Maximum Allowable Amount (ng/cm2)	Results (ng/cm2)
Total Organic Compound (TOC)	50	14.97
Compounds with RT ≤ DOP	NA	14.97
Compounds with RT > DOP	NA	0.00
Motor Base	Maximum Allowable Amount (ng/part)	Results (ng/part)
Repeated Hydrocarbon (C20-C40 Alkanes)	NA	Not Detected
	Maximum Allowable Amount (ng/cm2)	Results (ng/cm2)
Total Organic Compound (TOC)	50	19.58
Compounds with RT ≤ DOP	NA	11.62
Compounds with RT > DOP	NA	7.96

ADDRESS 75/37 Moo 11, Klong Nueng Subdistric, Klong Luang District, Pathumthani, Thailand 12120 | PHONE +66 2908 1681-5 | FAX +66 2908 1680

ALS Testing Services (Thailand) Co., Ltd. An ALS Limited Company




Page 2 of 3

ALS THAILAND REF NO.: ATT/ELP/14/4395-G
OUR REF NO.: ATS/ELT/0278/15
DATE: 01 April 2015

COMPANY: NMB-Minebea Thai Ltd.

File :C:\msdchem\l\data\Olmsfile\GCMS S\ELTO269,73,74,77,78\26-ELT ... 0278;60ml;BP.D Operator : VI-ALS(59) Clastrument : ATS-EL-0920 Acquired : 25 Mar 2015 7:55 Sample Name: ELTO278;NMB;60ml;BP Misc Info :






Page 3 of 3

ALS THAILAND REF NO.: ATT/ELP/14/4395-G
OUR REF NO.: ATS/ELT/0278/15
DATE: 01 April 2015

COMPANY: NMB-Minebea Thai Ltd.

File :C:\msdchem\1\data\01msfile\GCMS S\ELT0269,73,74,77,78\16-ELT ... 0278;Hub.D
Operator : \text{IL-ALS(S)}
Instrument : ATS-EL-0920
Acquired : 25 Mar 2015 00:08
Sample Name: ELT0278;NMB;10m1;Hub
Misc Info :



Note: This report was performed test by ALS Singapore. Remark: Minimum Detection Limit is 0.954 ng/part. Minimum RHC Detection Limit of Base is 0.008ng/cm2 Minimum RHC Detection Limit of Hub is 0.103ng/cm2

ALS Testing Services (Thailand) Co.,Ltd.

Warunee Maneesuwan M.Sc, B.Sc, Laboratory Manager

ADDRESS 75/37 Moo 11, Klong Nueng Subdistric, Klong Luang District, Pathumthani, Thailand 12120 | PHONE +66 2908 1681-5 | FAX +66 2908 1680

ALS Testing Services (Thailand) Co., Ltd. An ALS Limited Company