COLUMBIA, SOUTH CAROLINA AL-89 (FAA) 21364 WAAS 7001 Rwy Idg RNAV (GPS) RWY 5 APP CRS CH 45526 228 TDŻE 052° COLUMBIA METRO (CAE) W05A Apt Elev 236 V MALSR For uncompensated Baro-VNAV systems, LNAV/VNAV NA below MISSED APPROACH: Climb to 2400 Δ -15°C (5°F) or above 48°C (118°F). DME/DME RNP-0.3 NA. direct POMIE and on track 021° to \*\*RVR 1800 authorized with use of FD or AP or HUD to DA. BEFTY and hold. COLUMBIA APP CON GND CON **ATIS** COLUMBIA TOWER CLNC DEL **133.4 285.6** (290° 109° **124.15 338.2** (110° -289° 120.15 119.5 257.8 121.9 348.6 119.75 MISSED APCH FIX 4 NM -A BEFTY Procedure NA for arrivals at LEDAS on V155 southwest bound, and on V311 northwest bound **1**,746 R-6001 **LEDAS ∧**679 A & B 1,601 POMIE **^**413 TIBOC 2.5 NM to RW0.5 RW05 1156 1,525 **1**752 (FAF) **1**611 OTNOW **∧**720 (IAF) **∧**749 EBPEF RW 05 25 NZ Procedure NA for arrivals at (IF) ADCOM on V53 southeast bound. **EDURE** 3100 (IAF) **ADCOM** 2200 XEWO 275° **(** (15.2)ELEV 236 **TDZE 228** D 2400 POMIE BEFTY VGSI and RNAV glidepath not coincident (VGŠI Angle 3.00/TCH 73). Δ 396 021° **EDURE** OTNOW TIBOC \*LNAV only 2200 2.5 NM to TWR **RW05** 2200 052° \*1.3 NM to RW05 2200 RW05 GP 3.00° \*1080 TCH 60 052° to 3.4 NM 1.2 NM 1.3 NM CATEGORY LPV DA \*\* 428/24 200 (200-1/2) LNAV/ 638/50 410 (500-1) DΑ VNAV 700/40 700/50 LNAV MDA 700/24 472 (500-1/2) 472 (500-3/4) 472 (500-1)

COLUMBIA, SOUTH CAROLINA

740-1

504 (600-1)

860-1

624 (700-1)

Amdt 2D 30DEC21

CIRCLING

33°56′N-81°07′W

1040-21/4

804 (900-21/4)

1040-21/2

804 (900-21/2)

COLUMBIA METRO (CAE) RNAV (GPS) RWY 5

REIL Rwy 23

TDZ/CL Rwy 11

HIRL Rwys 5-23 and 11-29

to 10 AUG 2023

13 JUL 2023

SE-2,