EC-2, 13 JUL 2023 to 10 AUG 2023

8502 Rwy Idg APP CRS TDŹE 1008 005° Apt Elev 1009

RNAV (GPS) RWY 36

JAMES M COX DAYTON INTL (DAY) V For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -19°C (-2°F) or above 54°C (130°F). DME/DME RNP-0.3 NA. MISSED APPROACH: Climb to 3000 direct to KIRON and Rwy 36 helicopter visibility reduction below 3/4 SM NA. ATIS COLUMBUS APP CON DAYTON TOWER GND CON CINC DEL 119.9 257.7 125.8 118.425 323.15 121.9 121.75 NSA RW36 25 NZ MISSED APCH FIX 4 NM 3" 3100 \Diamond **KIRON** 1214 ∧ **∧**1333 **RW36** i163 (FAF) GUPNE 2049 (IF) Procedure NA for arrival **FOSDU** 3100 at CINPA on V47 southwest 068° bound. **ELEV 1009** TDZE 1008 14.6) D (IAF) CINPA 3000 KIRON **FOSDU GUPNE** 3100 0050 *1.4 NM *LNAV only to RW36 2700 RW36 4 GP 3.00° TCH 60 6 NM 3.7 NM -1.4 CATEGORY D LNAV 1449-11/2 441 (500-11/2) 005° VNAV 1500-11/4 1500-11/2 LNAV MDA 1500-1 492 (500-1) 492 (500-11/4) 492 (500-11/2)

C CIRCLING DAYTON, OHIO Amdt 1A 24MAY18 1580-1 571 (600-1)

JAMES M COX DAYTON INTL (DAY)RNAV (GPS) RWY 36

HIRL all Rwys

TDZ/CL Rwy 6L

REIL Rwys 6R and 36

1640-2

631 (700-2)

1580-11/2

571 (600-11/2)