NE-2,

13 JUL

. 2023

ಠ

6 AUG

RNAV (GPS) RWY 6

WAAS 10,014 Rwy Idg APCH CRS AL-150 (USAF) CH 91356 TDŹE 131 058° MC GUIRE FIELD (JOINT BASE MC GUIRE DIX LAKEHURST) (KWRI) W06A Arpt Elev 141 * When TDZ/CL lights inop, increase RVR to 24. When ALS inop, increase RVR to 40, vis ALSF-2 MISSED APPROACH: Climb to 2000 to 3/4 mile. direct DAYYO and hold. ** When ALS inop, increase vis to 1 1/4 miles. *** When ALS inop, increase CAT AB RVR to 55, vis to 1 mile; CAT CDE vis to 1 1/4 miles. (Å) ATIS MC GUIRE APP CON/DEP CON **TOWER GND CON** CLNC DEL PAR 110.6 270.1 126.475 363.8 118.65 255.6 121.8 275.8 135.2 335.8 **** Circling NA SE of Rwy 24 and E of Rwy 36 when R-5001 A/B Active. Alternate Missed Approach instructions: Climb to 2000 DME/DME RNP-0.3 NA direct DAYYO, expect further clearance from ATC. For uncompensated Baro-VNAV systems, Procedure NA below -15°C Missed approach holding at DAYYO NA when R-5001 is (5°F) or above 52°C (126°F). active with aerial gunnery. DAYYO RADAR required when R-5001 is active. RADAR required for holding above 2000 and/or > 230 KIAS. R5001 A & B If RADAR inoperative, expect 15 min delay for deactivation of R-5001. 06 R5001A (FAF) FENKA (IF/IAF) CISON NSA RW06 25 Ny RED LION **(** 300° CONTE (14.4) EMERG SAFE ALT 100 NM 5100 VGSI and RNAV glidepath not coincident (VGSI angle 2000 ELEV 141 **TDZE 131** DAYYO 3.00/TCH 76). BCN 306 CISON **FENKA** €236° 81 058° 2000 056°**∋** 1.1 NM to **RW06** RW06 2000 GP 3.00° TCH 56 -5.7 NM CATEGORY 331/18 200 $(200-\frac{1}{2})$ LPV DA* 560/40 LNAV/VNAV DA** 429 $(500-\frac{3}{4})$ LNAV MDA*** 560/24 429 (500-1/2) 560/40 429 $(500-\frac{3}{4})$ 700-11/2 700-2 1200-3 HIRL all Rwys 058° 680-1 539 (600-1) C CIRCLING **** 559 559 1059 **REIL Rwys 18, 36** $(600-1\frac{1}{2})$ (600-2)(1100-3)TDZL/CL Rwy 6

WRIGHTSTOWN, NEW JERSEY

MC GUIRE FIELD (JOINT BASE MC GUIRE DIX LAKEHURST) (KWRI)