WAAS CH 90414 W06B APP CRS TDZE 1009 061° Apt Elev 1009


RNAV (GPS) RWY 6R JAMES M COX DAYTON INTL (DAY)

For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -19°C (-4°F) or above 54°C (130°F). Rwy 6R helicopter visibility reduction below ¾ SM NA. Simultaneous approach authorized. DME/DME RNP-0.3 NA. LNAV procedure

MISSED APPROACH: Climb to 3000 direct TARRY and hold.

NA during simultaneous operations. Use of FD or AP required during simultaneous operations. **ATIS** COLUMBUS APP CON DAYTON TOWER GND CON CLNC DEL 125.8 118.425 323.15 119.9 257.7 121.9 121.75 MISSED APCH FIX **∧**1214 1333 1 TARRY RW06R (FAF) ĊIBLÓ (IF) EC-2, 13 JUL 2023 to 10 AUG 2023 **MEKTE** RW06R 25 Ny ^{∆2049} 3000 70658 ÁLIAS 3100 CAMMS A \bigcirc Procedure NA for arrivals at CAMMS on V275 southwest bound. **ELEV 1009** TDZE 1009

VGSI and RNAV glidepath not coincident (VGSI Angle 3.00/TCH 50).				3000	TARRY
ALI	IAS A	MEKTE			
3000	061° ->		CIBLO -		AV on l y.
3000	3000	0610		1.5 NM RW06R	
				↓ RV	V06R
GP 3.00° TCH 53		270	0		,,,,,,
	4.3 NM	- 6 NM	- 3.6 N	M 1.5-	-
CATEGORY	A	В	С		D
LPV DA	1259-¾ 250 (300-¾)				
LNAV/ DA VNAV	1496-1¾ 487 (500-1¾)				
LNAV MDA	1520-1 511 (600-1)		1520-1½		20-13/4
			511 (600-1½)	511 (600-1¾)
C CIRCLING	1580-1 5	571 (600-1)	1580-1½ 571 (600-1½)		40-2 (700-2)
PAGON ONO					



DAYTON, OHIO Amdt 1B 24MAY18 JAMES M COX DAYTON INTL (DAY) RNAV (GPS) RWY 6R