
5000 Rwy Idg APP CRS TDŻE 302 237° Apt Elev 302

V

RNAV (GPS) RWY 24 WOODWARD FLD (CDN)

MISSED APPROACH: Climbing left turn increase all MDAs 100 feet; increase LNAV and Circling visibility Cats to 3000 direct IBAYE and hold. **A**NA C/D ¼ SM. DME/DME RNP-0.3 NA. Visibility reduction by helicopters NA AWOS-3 SHAW APP CON★ UNICOM 119.975 125.4 318.1 123.0 (CTAF) (

When local altimeter setting not received, use Columbia altimeter setting and



CAMDEN, SOUTH CAROLINA Orig-A 20MAY21

MIRL Rwy 6-24 0

REIL Rwys 6 and 24 🗓

WOODWARD FLD (CDN) RNAV (GPS) RWY 24

498 (500-11/2) 900-2

598 (600-2)

498 (500-11/4)

840-11/2

538 (600-11/2)

800-1 498 (500-1)

840-1 538 (600-1)

LNAV MDA

CIRCLING