Δ

(IAF) ZÁMÁK

CÙBÓB

Rwy 10 helicopter visibility reduction below 3/4 SM NA. For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -16°C or above 54°C.

MISSED APPROACH: Climb to 3000 direct DIYZO and hold.

COLUMBUS APP CON **ASOS** UNICOM 128.725 121.825 323.15 122.7 (CTAF) (

JINAK



NoPT for arrival at UCAYU on V144 southeast bound. 3000 NoPT 86° (7)

(IF/IAF) FIPVA HOLD  $\frac{6000}{3000}$ UCAYU 1139± 1.9 NM to (FAF) BODYS **RW10** RW10 2400 096° 096° 989 (7.7)276°

DIYZO

**TDZE** 

961

EC-2, 13 JUL 2023 to 10 AUG 2023

1452 € Λ 1258 <sup>1982</sup>∧ 3000 NoPI 900 (7.1) (IAF)

3000 DIYZO 4 NM **UCAYU** Holding Pattern **BODYS** FIPVA 1.9 NM 6000 -·276° 2400 to RW10 \*LNAV only 3000 0960 \*1.3 NM to RW10 RW10 2400 GP 3.00° \*1580 TCH 45 7.7 NM 2.5 NM 0.6 1.3 NM

**☆** 1019 `096°

975

LPV 1211-1 250 (300-1) DA LNAV/ 1272-1 311 (300-1) DA VNAV

1420-1 459 (500-1)

REIL Rwys 10 and 28 0 HIRL Rwy 10-28 0

LNAV MDA LIMA, OHIO Amdt 1C 30JAN20

CATEGORY

LIMA ALLEN COUNTY (AOH) RNAV (GPS) RWY 10

1420-13/8 459 (500-13/8)

4 NM