SW-4,

13 JUL 2023

ō

10 AUG 2023

Rwy ldg 10,000 APCH CRS TDŹE 4346 MICHAEL AAF (KDPG) AL-5071 [USA] 122° Arpt Elev 4351 Obtain local altimeter setting on CTAF; when not received, use Wendover altimeter setting. MISSED APPROACH: Climb to 4760 then climbing right turn to 8500 direct ETUBY and hold, continue 🛕 NA climb in hold to 8500. DME/DME RNP-0.3 NA CLOVER CON CTAF 0 126.2 270.3 134.1 363.5 Procedure lies within R-6402A, PPR. † CAUTION: Missed Approach (IAF) Minimum Climb Rate to 6000 CEVAR BONNEVILLE 120 180 240 300 360 60 Knots BVL 6894 • 1685 V/V(fpm) 337 674 1011 1348 2022 8500 R-6405 R-6406B Procedure NA for arrivals on DTA VORTAC 5306 airways radials R-348 CW R-008 R-6406A (IAF/IF) 7 NM **ETUBY** 4348 R-6402B HISUK (FAF) R-6407 4597 UWOZO 12,200 HISUK ⇳ R-6402A VDP NA with Wendover VGSI and descent angles 4760 **ETUBY** not coincident altimeter setting minimums. **ETUBY UWOZO** 4351 4346 HISUK 122° from Rwy 12 ldg 10,000 Rwy 30 ldg 9998' FAF 3.00° 6100 TCH 55 CATEGORY Е LNAV MDA 4640-1 5140-21/2 794 (800-2½) 4800-1 4920-1 5160-21/2 5880-3 CIRCLING 809 (900-21/2 569 (600-1) 1529 (1600-3) †BELOW MINIMA REQUIRES MISSED APPROACH CLIMB GRADIENT of 337 ft/NM LNAV MDA (300-1) NA 4640-1 294 \* WENDOVER ALTIMETER SETTING MINIMUMS LNAV MDA 4800-1 454 (500-1) 5300-3 954 (1000-3) 5080-1 5320-3 6040-3 CIRCLING NA 969 (1000-3 TWR ☆ 4435 ⋂ TBELOW MINIMA REQUIRES MISSED APPROACH CLIMB GRADIENT of 337 ft/NM LNAV MDA 4800-3 (500-3) HIRL Rwy 12-30 🗓 NA 454

40°12′N-112°56′W

MICHAEL AAF