JACKSONVILLE, FLORIDA AL-5570 (FAA) 22307 RNAV (RNP) Y RWY 26 Rwy Idg 10000 APP CRS TDZE 27 257° Apt Elev JACKSONVILLE INTL (JAX) 30 RNP AR APCH-GPS MALSR MISSED APPROACH: Climb to For uncompensated Baro-VNAV systems, procedure NA 2000 on track 257° to UDAQI below -5°C or above 54°C. and hold D-ATIS JACKSONVILLE APP CON JACKSONVILLE TOWER GND CON CLNC DEL **CPDLC** 121.9 348.6 119.5 290.275 125,85 119.0 269.9 118.3 317.7 MISSED APCH FIX (IF) (IF) **UDAQ** NANAA LAYÓN (RNP 0.70) (RNP 0.70) 4000 3000 210K until JAAGS 210K until JAAGS 4 NM DABB 3100 (IF) YEJWO ADUYA (3.11 3000 (IF) 210K until JAAGS **EGAGE** (RNP 0.70) 4000 1800 210K until JAAGS 257° 15.31 DEYER XIVXU 1100 (1.4)(FAF) JAAGS **RW26** (3.2) ^⁴⁵¹ ۸²⁷⁶ ..257 ZALAM RW 26 25 Mg ۸²⁸⁰ ELEV 30 **TDZE** ∆⁶⁵⁹ 2700 257 (IF) GUTNE 4000 210K until JAAGS UDAQI VGSI and RNAV glidepath not coincident 2000 (VGSI Angle 3.00/TCH 70). **JAAGS** tr 257° 1100 See planview for multiple IF locations. 1100 RW26 GP 3.00° TCH 49 3 2 NM CATEGORY D 419/35 392 (400-%) **REIL Rwy 32** RNP 0.30 DA TDZ/CL Rwys 8, 14, and 26

HIRL Rwys 8-26 and 14-32 JACKSONVILLE, FLORIDA Amdt 1B 02DEC21 AUTHORIZATION REQUIRED

to 10 AUG 2023

13 JUL 2023

SE-3,