v

SW-1, 13 JUL 2023 to 10 AUG 2023


Rwy Idg 12000 APP CRS TDŹE 5392 173° Apt Elev 5434

RNAV (RNP) Z RWY 17R

DENVER INTL (DEN)

GPS required. For inoperative MALSR, increase RNP 0.10 all Cats visibility MALSR to RVR 5000 and RNP 0.30 all Cats visibility to 1% mile. Simultaneous approach authorized. Use of FD or AP providing RNAV track guidance required during simultaneous operations. For uncompensated Baro-VNAV systems, procedure NA below -25°C (-13°F) or above 45°C (114°F).

MISSED APPROACH: Climb to 10000 on track 173° to JAKUR and on track 200° to HOHUM and hold.



26, 34L, 34R, 35L, 35R DENVER, COLORADO Orig-C 01FEB18

TDZ/CL Rwys 7, 16L, 16R, 17R,

HIRL all Rwys

DENVER INTL (DEN)

AUTHORIZATION REQUIRED

5894/60 502 (500-11/4)

RNP 0.30 DA