SC-4, 13 JUL 2023 to 10 AUG 2023

8003 Rwy Idg APP CRS TDŹE 261 CH **99600** 002° Apt Elev 264 W36A

RNAV (GPS) RWY 36

GOLDEN TRIANGLE RGNL (GTR) RNP APCH For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -15°C or above 54°C MISSED APPROACH: When local altimeter setting not received, use Columbus AFB altimeter setting: increase LPV Climb to 3000 direct Α DA to 500 feet, LNAV/VNAV DA to 593 feet and LNAV/VNAV visibility 1/8 SM; increase HUYKA and hold. all MDAs 40 feet. Baro-VNAV and VDP NA when using Columbus AFB altimeter setting COLUMBUS APP CON * **ATIS** GOLDEN TRIANGLE TOWER★ **GND CON** CLNC DEL 126,375 135.6 323.275 118.2 (CTAF) 0 298.875 135,375 322,475 135,375 322,475 CLNC DEL MISSED APCH FIX UNICOM A-440 126,25 122.95 7 NM (when twr closed) A-440 HUYKA -⁵⁹³∧ Λ449 30 NM to DIXV 372± JAKVU 2.7 NM to RW36 3000 ∆¹⁰⁰⁵ DIXVU (FAF) BAWMO ۸₈₅₄ 092 272° DIXVU (IF/IAF) 3000 DIXVU PONT TO DIXVU INOP 264 TDZE 261 HOLD $\frac{6000}{3000}$ 3000 HUYKA VGSI and RNAV glidepath not coincident (VGSI Angle 3.00/TCH 55). 7 NM DIXVU Holding Pattern **BAWMO** JAKVU * LNAV only 2.7 NM to 6000 ←182° 2000 RW36 3000 *1 NM to RW36 TWR 346 **RW36** GP 3.00° 2000 *1140 TCH 42 6.3 NM 27 NM +1.7 NM→ CATEGORY B D Α Е LPV DA 461-3/4 200 (200-3/4) LNAV 554-78 293 (300-7%) VNAV LNAV MDA 640-1 379 (400-1) 640-11/8 379 (400-11/8) 002° to 960-21/2 RW36 960 - 2960-21/4 CIRCLING 760-1 496 (500-1) 696 (700-2) 696 (700-21/4) 696 (700-21/2 HIRL Rwy 18-36 (