EC-1, 13 JUL 2023 to 10 AUG 2023

D

NA

NA

NA

WAAS 5056 Rwy Idg TDZE APP CRS CH **49122** 716 323° Apt Elev 716 W32A RNP APCH

RNAV (GPS) RWY 32 SAULT STE MARIE MUNI/SANDERSON FLD (ANJ)

MISSED APPROACH: Climb Rwy 32 helicopter visibility reduction below 3/4 SM NA. When local altimeter setting to 2800 direct KUCEB and

V not received, use Chippewa County Intl altimeter setting and increase all MDA 60 feet, Δ hold. and increase LP Cat C visibility 1/8 mile and LNAV Cat C visibility 1/4 mile. **ASOS** UNICOM **TORONTO CENTER** 122.7 (CTAF) 0 132.65 344.5 118,375 ۸¹⁶⁴¹ ۸¹⁵⁸⁶ 1517 ^A A925 **CUXIG** 1.7 NM 764± to RW32 (FAF) 950 YIRUĆ SAULT STE MARIE 3100 Procedure NA for arrivals 133° (6.7) on SSM VOR/DME airway MSA RW32 25 radials 080 CW 201. ZIDVI 3100 ELEV 716 TDZE 716 PINES HITAM 2800 KUCEB 4 NM ZIDVI Holding Pattern YIRUC CUXIG 1.7 NM to RW32 <3.00° TCH 30 2200 RW32 1280

←1.7 NM-

CATEGORY

LNAV MDA

CIRCLING

MDA

-2.9 NM

1200-1 484 (500-1)

1280-1 564 (600-1)

Α

SAULT STE MARIE, MICHIGAN Orig-B 08NOV18

MIRL Rwy 14-32 (

REIL Rwys 14 and 32 0

323° 4.6 NM

from FAF

SAULT STE MARIE MUNI/SANDERSON FLD (ANJ)

1200-1%

484 (500-1%) 1320-13/4

604 (700-13/4)

6.1 NM

1040-1 324 (400-1)