
Rwy 25 helicopter visibility reduction below 3/4 SM NA. Obtain local altimeter setting on CTAF; when not received, procedure NA. Uncontrolled airspace below 5500.

MISSED APPROACH: Climb to 1700 direct OGEVE and hold.

MAJURO RADIO 123.6 (CTAF) 0



MAJURO ATOLL, MH Orig-F 14JUL22

MIRL Rwy 7-25

REIL Rwys 7 and 25 0

7913 X 150

AMATA KABUA INTL (MAJ)(PKMJ)

520-11/2

513 (600-11/2)

066°

460-13/8 453 (500-13/8)

14000

1700

560-2

553 (600-2)

07°04′N-171°16′E

1.3 NM to

RW25

-1 3+

CATEGORY

LNAV MDA

**C** CIRCLING

1700

4.9 NM

≤ 3.00° TCH 54 -3.9 NM

460-1 453 (500-1)

520-1 513 (600-1)