RNP APCH.

SE-3, 13 JUL 2023 to 10 AUG 2023


LAKELAND, I	LONIDA		
WAAS CH 77805 W23A	APP CRS 231°	Rwy Idg TDZE Apt Elev	5000 141 142

RNAV (GPS) RWY 23 LAKELAND LINDER INTL (LAL)

T For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -15°C or above 54°C. When local altimeter setting not received, use Plant City altimeter setting: increase LPV DA to 444 feet; increase LNAV/VNAV DA to 540 feet; increase all MDAs 20 feet and LNAV Cat C/D and

MISSED APPROACH: Climb to 2000 direct BIYAT and right turn on track 330° to

ATIS 118.025	TAMPA APP CON 120.65 290.3	LAKELAND TOWER 124.5 236.775	GND CON 121.4
& & & & & & & & & & & & & & & & & & &	292 A C 185 A RW23 A 288 A 411 A 548	5 NM (IF/IAF) JOVMU	30 N/M 6 O ZZ Z
V 142 D TDZE	141		
TWR 285	2000 BIYAT tr 330°	tr (VGSI A	d RNAV glidepath not coinc ngle 3.00/TCH 46). DVMU 5 NM Holding Pa



LAKELAND, FLORIDA Orig-H 08SEP22

LAKELAND LINDER INTL (LAL) RNAV (GPS) RWY 23

698 (700-21/4)

578 (600-1%)