EC-2, 13 JUL 2023 to 10 AUG 2023

WAAS Rwy Idg 4502 APP CRS CH **86514** 760 TDZE 095° W09A Apt Elev 763

RNAV (GPS) RWY 9 PUTNÁM COÚNTY (OWX)

RNP APCH

V AN A

For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -16°C or above 54°C Rwy 9 helicopter visibility reduction below 3/4 SM NA. Baro-VNAV and VDP NA when using Findlay altimeter setting. When local altimeter setting not received, use Findlay altimeter

MISSED APPROACH: Climb to 3000 direct CIVRO and hold.

setting and increase all DAs/MDAs 40 feet. AWOS-3 TOLEDO APP CON UNICOM 120,525 120.8 317.55 122.7 (CTAF) (MISSED APCH FIX Procedure NA for arrivals at TWERP on V8-422 westbound. 4 NM (IAF) TWERP 1817_A 3000 NOPT CIVRO Λ^{1026} **ILEDE** (IF/IAF) 2.5 NM to RW09 WIFES 2500 1009 095° **X**RW09 (6.2) 955 812± (FAF) ZEBIR 1143 4 NM Λ^{1271} NSA RW09 25 Ny 3000 \Diamond ELEV 763 TDZE 760 CIVRO 4 NM 3000 WIFFS Holding Pattern ZEBIR ILEDE 095° 4502 X 75

1				ILL	.UL		
	275° 095° - 095°				√M to √09	*LNAV only.	
3000			*1 NM to RW09				
<u>GP 3.00</u> ° TCH 40		2	500	*1580	_	RW09	
		,	− 6.2 NM 	2.8 NM	 1.5	1.0	
CATEGORY	A		В	С С	C D		
LPV DA	1048-1 288 (300-1)				NA		
LNAV/ VNAV DA	1147-1½ 387 (400-1½)				NA		
LNAV MDA	1120-1 360 (400-1)				NA		
CIRCLING	1200-1 1220-1 437 (500-1) 457 (500-1)				NA		
OTTAWA, OH	0		•			•	

REIL Rwys 9 and 27 MIRL Rwy 9-27 () PUTNAM COUNTY (OWX) RNAV (GPS) RWY 9