Rwy Idg

Apt Elev

COLUMBUS APP CON

125.95 371.975

TDŻE

APP CRS

281°

BOUTN

10113

2049

1129

815

815

Simultaneous approach authorized. For uncompensated Baro-VNAV systems, LNAV/

VNAV NA below -19°C or above 54°C. LNAV procedure NA during simultaneous

operations. Use of FD or AP providing RNAV track guidance required during simultaneous operations. For inop ALS, increase LNAV Cat C/D visibility to 1% SM.

COLUMBUS TOWER

132,7 257,8

∧ 1503

∆1196

ZIGT

۸¹²⁸⁰

WAAS

CH 48999

W28A

D-ATIS

124.6

MISSED APCH FIX

RNP APCH

CPDLC

EC-2, 13 JUL 2023 to 10 AUG 2023

4 NM

Holding Pattern

6000

3300

GP 3.00°

TCH 52

505 (600-1)

1520-21/4

705 (800-21/4)

RNAV (GPS) Y RWY 28L

MALSR

BAZE

2

ž

ŝ

2300

BAZEL

200 (200-1/2)

422 (500-3/4)

VGSI and RNAV glidepath not coincident

(VGSI Angle 3.00/TCH 68).

1560

ZIGTI 2.2 NM to

RW28L *1.4 NM to

RW28L

LMITD

2300

1015/18

1237/40

505 (600-1/2)

525 (600-1)

GND CON

121.9 348.6

JOHN GLENN COLUMBUS INTL (CMH)

LOM and hold.

CLNC DEL

126.3

3300

BAZEL →

MISSED APPROACH: Climb

to 1400 then climbing left

turn to 3000 direct BOUTN

13 JUL 2023 to 10 AUG 2023

TDZ/CL Rwy 10R-28L

HIRL Rwys 10R-28L and 10L-28R

815

1026

TDZE D

815

8 (A

281° to RW28L 1400

3000

*LNAV only.

CATEGORY LPV

DΑ

LNAV/

VNAV

LNAV MDA

CIRCLING

BU

О

RW281

1320/55

1520-2

705 (800-2)

1320/24

1340-1