3rd Party Transceivers / service unsupported-transceiver

ARISTA

- 1. Login as admin;
- 2. Enable privileged access;
- 3. Go to the bash shell;
- 4. Touch the filename /mnt/flash/enable3px;
- 5. Reboot the switch.

Below is a session from EOS-4.11.6:

localhost login: admin
localhost>ena
localhost#bash

Arista Networks EOS shell

[admin@localhost ~]\$ touch /mnt/flash/enable3px
[admin@localhost ~]\$ sudo reboot

CISCO

service unsupported-transceiver