

Document Name: OPERATING GUIDELINES FOR PRESSURE TEST ADAPTORS
TC6A-349 AND TC6A-797

Document Number: E1A4041813

Revision	Author	Checker	Approver	Issue Date
A	D. M ^c DOUGLE	C. HARRISON	S. KELLY	07/05/2024
	INITIAL ISSUE			

REVISION CONTROL: History of Revision Control is Managed by the Document Management System.

1 PURPOSE & SCOPE

The purpose of this procedure is to detail the process for the use of pressure test adaptors TC6A-349 and TC6A-797 with connectors requiring hydrostatic pressure testing during installation. The applicable connectors are listed in the relevant adaptor product datasheet (PDS).

2 ASSOCIATED DOCUMENTS AND DRAWINGS

Number	Name	Location
10009195	TC6A-797 PDS	Teamcenter
SD00021194	TC6A-349 PDS	Teamcenter
T14850	TC6A-349 Drawing and Associated BOM	Teamcenter
T20448	TC6A-797 Drawing and Associated BOM	Teamcenter
10204852	ElectRON Installation, Operations and Maintenance Manual	Siemens-energy.com/subsea

3 EQUIPMENT

The following equipment will be required to complete this installation:

- Calibrated 16 mm spigot torque wrench Part No. NOR-13019 (15 to 80 lbf ft) (or equivalent)
- 3/4" A/F open end fitting Part No. NOR-29709 (or equivalent)
- 5 mm Allen Key

4 GENERAL SAFETY INFORMATION AND RISKS

1. For full Safety and Hazard information, please consult the ElectRON IOM or Safety Data Sheet for the test media in use.

	Warning. Risk of minor personal injury to persons with sensitivities to mineral based oils. Wear appropriate hand protection when handling products or mineral or synthetic based oils.
	Warning. Risk of minor personal injury and/or material or environmental damage during assembly. Caution shall be exercised during assembly to ensure that fittings and hydraulic/pneumatic equipment are correctly installed.
	Warning. Risk of bodily injury caused by pressure retaining parts becoming projectile due to user over-pressurising the system.
	Warning. Hydraulic injection risk. Only to be used to MAWP with oil and suitable pump in lines with Pressure Equipment (Safety) Regulations (2016) or relevant local alternative where used abroad.

5 PREPARATION

1. Visually inspect the adaptor assembly, ensure there is no damage to the sealing cone, threads, or body of the adaptor. If there is any doubt over the integrity of the adaptor, stop work immediately and contact the Siemens Energy Technical Department.

6 PROCESS

1. Refer to the relevant assembly/installation procedure and connector/scope drawing for the test pressure to be used and location of the test port.
2. Loosely fit the test adaptor being used to the connector under test.
3. For the TC6A-349, tighten the grub screw hand tight only (4 Nm) using a 5 mm Allen key to take up any slack in the connection.
4. Tighten the test fixture to 5 to 10 Nm using torque wrench NOR-13019 and 3/4" adaptor NOR-29709.
5. Perform pressure test in accordance with relevant assembly/installation procedure.
6. Relieve system pressure down to ambient.
7. Remove test adaptor from connector under test and clean up any residual oil on the connector and adaptor.

END OF PROCEDURE