

SoD + FDMA debug budget

S	= 1
sensor_index	= 0
B_total	= 5.000000e+03
B_sensor	= 5.000000e+03
P_per_sensor	= 1.000000e+00
N0	= 1.000000e-02
SNR_sensor	= 2.000000e-02
SNR_sensor_dB	= -16.989700
C_sensor	= 1.428458e+02 bit/s
tau	= 1.000000e+00 s
available_bits_per_tau	= 1.428458e+02
M_benchmark_per_sensor	= [19956]
event_count	= 85
amplitude_bits_per_event	= 14.284535
time_bits_per_event	= 8.700440
total_bits_per_event	= 22.984975
payload_bits	= 1.953723e+03
payload_feasible	= False