
Discrete PID Controller

for use in Robotics Project #3

Outline

- Discrete Time Integrals and Derivatives
- Z-Transform
- Discrete TF of Integrals and Derivatives
- Discrete TF of PID
- Implementation of Digital PID
- Control Signal Limit (Saturation)

Discrete Time Integrals and Derivatives



Discrete Time Integrals and Derivatives (cont.)

Discrete Time Derivative:

$$y(k) \approx \frac{f(k) - f(k-1)}{T_s}$$

Discrete Time Integral (Trapezoidal):

$$\int_0^{k*Ts} y(t)dt = y(k) \approx y(k-1) + \frac{f(k) + f(k-1)}{2} * T_s$$

z-Transform

$$X[z] = \mathcal{Z}\{x[k]\} = \sum_{k=0}^{\infty} x[k]z^{-k}$$
$$z = A e^{j\theta} = A(\cos(\theta) + j\sin(\theta))$$

Time shifting property:

$$\mathcal{Z}\{x[k-n]\} = z^{-n} X[z], where,$$

 $\mathcal{Z}\{x[k]\} = X[z]$

Discrete TF of Integrals and Derivatives

Discrete TF of Derivative:

$$y(k) = \frac{f(k) - f(k-1)}{T_s}$$

$$Y[z] = \frac{F[z] - z^{-1}F[z]}{T_s}$$

$$\frac{Y[z]}{F[z]} = \frac{z-1}{z T_s}$$

Discrete TF of Integrals and Derivatives (cont.)

Discrete TF of Integral:

$$y(k) = y(k-1) + \frac{f(k) + f(k-1)}{2} T_s$$

$$Y[z](1-z^{-1}) = \frac{T_s}{2} F[z](1+z^{-1})$$

$$\frac{Y[z]}{F[z]} = \frac{T_s}{2} \frac{z+1}{z-1}$$

Discrete TF of PID

$$\begin{split} &\frac{U[z]}{E[z]} = K_p + K_i \frac{T_s}{2} \frac{z+1}{z-1} + K_d \frac{z-1}{z T_s} \\ &\frac{U[z]}{E[z]} = \frac{K_p(z^2 - z) + K_i \frac{T_s}{2} (z^2 + z) + \frac{K_d}{T_s} (z^2 - 2z + 1)}{z^2 - z} \\ &\frac{U[z]}{E[z]} = \frac{\left(K_p + K_i \frac{T_s}{2} + \frac{K_d}{T_s}\right) z^2 + \left(-K_p + K_i \frac{T_s}{2} - \frac{2K_d}{T_s}\right) z + \frac{K_d}{T_s}}{z^2 - z} \end{split}$$

Implementation of Digital PID

$$\frac{U[z]}{E[z]} = \frac{\left(K_p + K_i \frac{T_s}{2} + \frac{K_d}{T_s}\right) z^2 + \left(-K_p + K_i \frac{T_s}{2} - \frac{2K_d}{T_s}\right) z + \frac{K_d}{T_s}}{z^2 - z}$$

$$\frac{U[z]}{E[z]} = \frac{\left(K_p + K_i \frac{T_s}{2} + \frac{K_d}{T_s}\right) + \left(-K_p + K_i \frac{T_s}{2} - \frac{2K_d}{T_s}\right) z^{-1} + \frac{K_d}{T_s} z^{-2}}{1 - z^{-1}}$$

$$U[z] = z^{-1} U[z] + a E[z] + b z^{-1} E[z] + c z^{-2} E[z]$$

$$u[k] = u[k - 1] + a e[k] + b e[k - 1] + c e[k - 2]$$

$$a = \left(K_p + K_i \frac{T_s}{2} + \frac{K_d}{T_s}\right)$$

$$b = \left(-K_p + K_i \frac{T_s}{2} - \frac{2K_d}{T_s}\right)$$

$$c = \frac{K_d}{T_s}$$

Control Signal Limit (Saturation)

Is control signal within limits? If not, limit the control signal by the maximum value that can be achieved:

```
if fabs(u) >= uMax
u = u/fabs(u)*uMax;
```
