INSPECTION REPORT

Roof Condition Report - RTB Roofing

RTB Roofing Ltd · Studley Rd, London, SW4 6RZ

Roof Condition Report - RTB Roofing	Complete
Site Address	Rear elevation, scaffold lift 3
Date of Survey	04 Nov 2026
Surveyor from RTB	Andy Admin

Roof Condition Report - RTB Roofing

Condition key

- Satisfactory
- Repair Required
- Replacement should be planned
- Immediate replacement

Roof Drawing / Mark-up

Roof drawing / mark-up (upload the A3 drawing, PDF or photo) - Roof Condition Report - RTB Roofing



Generated via OpHUB

Roof Condition Report - RTB Roofing

RTB Roofing Ltd · Studley Rd, London, SW4 6RZ

Roof Survey Area 1

Description of Surveyed Area

Slates slipped near the valley; battens sound. Lead flashing to the chimney needs re-dressing.

Item 1

Slates slipped near the valley; battens sound. Lead flashing to the chimney needs re-dressing.

Item 2

Slates slipped near the valley; battens sound. Lead flashing to the chimney needs re-dressing.

Item 3

Slates slipped near the valley; battens sound. Lead flashing to the chimney needs re-dressing.

Item 4

Slates slipped near the valley; battens sound. Lead flashing to the chimney needs re-dressing.