



PONDERA PINOUT

CN2:

- 1- GND
- 2- GND
- 3- EXT+
- 4- EXT-
- 5- SIG-
- 6- SIG+

CN1:

- 1- RS485_P
- 2- +5V
- 3- RS485_N
- 4- +5V
- 5- GND
- 6- GND
- 7- OUT
- 8- IN
- 9- TX
- 10- RX