
24 wafers | H=10 | Pure 2x2; waiting allowed
Cmax = 1237 s
ATR robot
AL
LLupper slot 1
LLupper slot 2
VTR robot
CH2 PM
CH3 PM
LLlower slot 1
LLlower slot 2
0
309
618
928
1237
Time / s
Cmax 1237 s | WPH 69.85 | Displayed horizon 1237 s
ATR pick
ATR loaded move
ATR place / AL
AL wafer exchange
LL pump
LL vacuum wait
LL vent
LL atmosphere wait
VTR / LL load
VTR loaded / bridge
VTR unload
PM process / PEC support
Chamber wait
Chamber exchange / rotation
LL pressure reset
Robot empty movement