
24 wafers | H=10 | Pure 4x1
Cmax = 1268 s
ATR robot
AL
LLupper slot 1
LLupper slot 2
VTR robot
CH2 PM
CH3 PM
LLlower slot 1
LLlower slot 2
0
317
634
951
1268
Time / s
Cmax 1268 s | WPH 68.14 | Displayed horizon 1268 s
ATR pick
ATR loaded move
ATR place / AL
AL wafer exchange
LL pump
LL vacuum wait
LL vent
LL atmosphere wait
VTR / LL load
VTR unload
PM process / PEC support
Chamber wait
LL pressure reset
Robot empty movement