
8 wafers | H=3 | Pure 4x1
Cmax = 610 s
ATR robot
AL
LLupper slot 1
LLupper slot 2
VTR robot
CH2 PM
CH3 PM
LLlower slot 1
LLlower slot 2
0
152
305
458
610
Time / s
Cmax 610 s | WPH 47.21 | Displayed horizon 610 s
ATR pick
ATR loaded move
ATR place / AL
AL wafer exchange
LL pump
LL vacuum wait
LL vent
LL atmosphere wait
VTR / LL load
VTR unload
PM process / PEC support
Chamber wait
LL pressure reset
Robot empty movement