
1
D
D
P1
P1
Load dummy PW pair D
rotate chamber
load P1
2
D
D
P1
P1
Process / rotation
D + P1
P1 exposure 1
3
P1
P1
P2
P2
Chamber rotation
+ chain slide
P1 + P2
4
P1
P1
P2
P2
Chamber
processing
P1 exp. 2 / P2 exp. 1
5
P2
P2
P3
P3
Chamber rotation
+ chain slide
P2 + P3
6
P2
P2
P3
P3
Chamber
processing
P2 exp. 2 / P3 exp. 1
7
P3
P3
D
D
Chamber rotation
+ chain slide
P3 + D
8
P3
P3
D
D
Chamber
processing
P3 exposure 2
9
Unload all
chamber empty