
## Two-Stage Miller-Compensated OTA with pMOS Input Stage



Note: Do not connect a BUS directly to VDD or VSS even with a jumper. Use the Chip\_VDD and Chip\_VSS.

.global VDD .param VDD = 2.5 .inc transistor\_models\_tsmc025\_public.inc

<sup>\*.</sup>step param Ccomp list 100f 100p 200p 400p \*.step param Rcomp list 0.001 200 \*.ac dec 50 1 1e9