

			C2	
			P18 P16 P19 P17	P25 P24 P20 P21
		SDA SCL GND +5V	Ports	P29 P28 P27 P26
Smart Motor ber In 9U	+	RX2 TX2 VMOT GND P30 P19 GND	Digital IO P32 G 5V S A P32 B	P33 P32 P31 P30
3 OC Motor A aber In From Saber	M+ M-	+5V M+ M- P29 P18 GND	P31 C P30 D P37 E P36 F	P37 P36 P35 P34
: Motor B From Saber	M+	+5V M+ M-	р р р р р р р р р р р р р р	