
Colourupter Component Sorting Sheet


For the full, step-by-step assembly guide, visit diy.re/colourupter-manual



Standoffs, Header, and IC Socket








IC1

IC Socket



3

Capacitors, Vactrol, Trimpot



VR1 2k trimpot



Marking: 202



Integrated circuit

IC1 TL084 Opamp



