DOA Colour
Component Sorting Sheet

For the full, step-by-step assembly guide, visit
diy.re/doa-manual

1 Connectors

CON1
8-pin header

Snap-in standoffs



DOA sockets

2 Resistors



3 Capacitors

C1, C2
100pF ceramic caps



C3-C5
100uF caps



C6
470uF cap

Discrete Opamp (Optional)

DOA pins

R11, R12
5.6R 1W



Q1, Q2
BC550C



Q7
BD139



Q8
BD140