JFT Colour

Component Sorting Sheet

For the full, step-by-step assembly guide, visit diy.re/jft-manual





Snap-in standoffs











2 Resistors







3

Capacitors, Transistor









C5 .1uF film cap



C7 22pF ceramic cap



T1 2SK170 JFET



T2, T3, T5, T6 BC327



T4

BC337 (marked with silver on top)

