
PR502

Component Sorting Sheet

For the full, step-by-step assembly guide, visit diy.re/pr502-manual


1

Resistors and Diode




2

Capacitors, LEDs, Switches, and Inductors





Capacitors, LEDs, and Power Resistors continued







XLR Jacks and Standoff

J2, J4 3-pin XLR female





J1, J3 3-pin XLR male





J6 5-pin XLR male







Standoff Screw




Standoffs



4 Card Edge Connectors

Card edge connectors



Card edge screws



Card edge bracket



H1-H4 L-bracket to MB screws




CON1, CON2 Headers to connect daughterboard




5 Chassis Screws

Front panel screws



Jack rear panel screws



Rear panel screws



Lock washers



