LC-3 Instruction Set

	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0	
ADD	0	0	0	1	DR			SR1		0	0	0	SR2				
ADD	0	0	0	1	DR			SR1			1	imm5					
AND	0	1	0	1	DR			SR1			0	0	0 SR2				
AND	0	1	0	1	DR				SR1 1 imm5								
BR	0	0	0	0	n	Z	р	PCoffset9									
JMP	1	1	0	0	0	0	0	BaseR			0	0	0	0	0	0	
JSR	0	1	0	0	1			PCoffset11									
JSRR	0	1	0	0	0	0	0	BaseR		0	0	0	0	0	0		
\underline{LD}	0	0	1	0		DR		PCoffset9									
LDI	1	0	1	0	DR			PCoffset9									
LDR	0	1	1	0	DR				BaseR offset6								
\overline{LEA}	1	1	1	0	DR			PCoffset9									
NOT	1	0	0	1		DR			SR		1	1	1	1	1	1	
RET	1	1	0	0	0	0	0	1	1	1	0	0	0	0	0	0	
RTI	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
ST	0	0	1	1		SR		PCoffset9									
STI	1	0	1	1	SR			PCoffset9									
STR	0	1	1	1	SR				BaseR offset6								
TRAP	1	1	1	1	0	0	0	0	0 trapvect8								
null	1	1	0	1													

- <u>Underlined</u> instructions set the condition code.
- Italicized instructions use a program counter offset.
- Non-register sources are signed, 2's complement, sign-extended integers.