

Entry Actions:
 Check temp vs setPoint, set Blue LED behavior:
 if temp > setPoint: LED pulse
 else: LED solid

Events:
 redButton: setPoint++, update LED
 blueButton: setPoint--, update LED
 Every 10s: Recheck temp, update LED

Outputs:
 LCD output:
 Line 1: Display date & time
 Line 2: Alternates every 5 sec between current temp
 and mode/setPoint
 Blue LED: pulse or solid (based on temp vs setPoint)
 Every 30 sec: UART transmit (mode, temp, setpoint)


Exit Actions: Blue LED off

Entry Actions:
 Check temp vs setPoint, set Red LED behavior:
 if temp < setPoint: LED pulse
 else: LED solid

Events:
 redButton: setPoint++, update LED
 blueButton: setPoint--, update LED
 Every 10s: Recheck temp, update LED

Outputs:
 LCD output:
 Line 1: Display date & time
 Line 2: Alternates every 5 sec between current temp
 and mode/setPoint
 Red LED: pulse or solid (based on temp vs setPoint)
 Every 30 sec: UART transmit (mode, temp, setpoint)

Exit Actions: Red LED off



Entry Actions:
 Blue LED and Red LED off

Events:
 redButton: setPoint++
 blueButton: setPoint--

Outputs:
 LCD output:
 Line 1: Display date & time
 Line 2: Alternates every 5 sec between current temp and
 mode/setPoint
 Every 30 sec: UART transmit (mode, temp, setpoint)