

Entry Actions:
Check temp vs setPoint, set Blue LED behavior:
if temp > setPoint: LED pulse
else: LED solid

Events:
redButton: setPoint++, update LED
blueButton: setPoint--, update LED
Every 10s: Recheck temp, update LED

Outputs:
LCD output:
Line 1: Display date & time
Line 2: Alternates every 5 sec between current temp
and mode/setPoint
Blue LED: pulse or solid (based on temp vs setPoint)
Every 30 sec: UART transmit (mode, temp, setpoint)


Exit Actions: Blue LED off

Entry Actions:
Check temp vs setPoint, set Red LED behavior:
if temp < setPoint: LED pulse
else: LED solid

Events:
redButton: setPoint++, update LED
blueButton: setPoint--, update LED
Every 10s: Recheck temp, update LED

Outputs:
LCD output:
Line 1: Display date & time
Line 2: Alternates every 5 sec between current temp
and mode/setPoint
Red LED: pulse or solid (based on temp vs setPoint)
Every 30 sec: UART transmit (mode, temp, setpoint)

Exit Actions: Red LED off



Entry Actions:
Blue LED and Red LED off

Events:
redButton: setPoint++
blueButton: setPoint--

Outputs:
LCD output:
Line 1: Display date & time
Line 2: Alternates every 5 sec between current temp and
mode/setPoint
Every 30 sec: UART transmit (mode, temp, setpoint)