## **Untitled Gantt Project**

Jan 11, 2019

http://

Project manager

**Project dates** Jan 7, 2019 - Mar 18, 2019

Completion2%Tasks24Resources0

## Tasks

Name	Begin date	End date	
Statement of Work	1/7/19	1/20/19	
1st draft of SOW	1/7/19	1/13/19	
Complete SOW	1/14/19	1/20/19	
Qgroundcontrol learning	1/7/19	1/20/19	
Pixhawk 4 learning	1/14/19	2/3/19	
Pixhawk 4 Learning	1/14/19	1/27/19	
Pixhawk 4 arrive at Sightline	1/27/19	2/3/19	
Working with Pixhawk 4	1/27/19	2/3/19	
Quadcopter learning	1/21/19	2/3/19	
Expect Quadcopter arrive at Sightline	1/21/19	1/27/19	
Working with Quadcopter	1/21/19	2/3/19	
Code wring	1/21/19	3/10/19	
Learn from sample code	1/21/19	2/3/19	
Start wring a new code and debug	2/4/19	3/10/19	
Create a new schematic for AB board	1/28/19	3/17/19	
Start drawing a schematic for AB board	1/28/19	2/10/19	
Send schematic for manufacturing	2/11/19	2/24/19	
Schematic test and debug	2/25/19	3/17/19	
Test and simulate indoor (Pixhawk 4 + Qground Control +Quadcopter)	2/4/19	3/10/19	
Learn how to connect all hardware together	2/4/19	2/10/19	
Hardware + simulation model using Qgroundcontrol	2/11/19	3/3/19	
Indoor test	3/4/19	3/10/19	


## Tasks

Name	Begin date	End date
3D enclosure create	3/4/19	3/17/19
First demo	3/11/19	3/17/19

11, 2019

**Gantt Chart** 





## **Untitled Gantt Project**

Jan 11, 2019

**Resources Chart** 

GANTT	January 2019				February 2019	ebruary 2019			March 2019	March 2019	
project	Week 2	Week 3	Week 4	Week 5	Week 6	Week 7	Week 8	Week 9	Week 10	Week 11	
Name	Default role	1/13/19	1/20/19	1/27/19	2/3/19	3/10/19	2/17/19	3/24/19	3/3/19	3/10/19	

5