

## Crownfire

180 Trowers Rd Unit 16 Vaughan, Ontario L4L 8A6 Brandford: (519) 756-8962 Toronto: (416) 665-6555 Woodbridge: (905) 851-9119 Toll free: 1-877-243-9664 Website: www.crownfire.ca

## **Fire Hydrant Inspection Report**

Customer Name:MAPLE LEAF FOODSTechnician:MATT DAVISAddress:15350 OLD SIMCOE RDInspection Date:AUGUST 16, 2012

Fire Hydrant Location Technician Comments

ALL OK

Fire Hydrant Make And Model: CENTURY 2000

## **Valve Testing**

Size of Test Valve	3/4"	1"
Static Pressure		65
Residual Pressure		55
Pito Pressure		30
G.P.M. Pressure		105
Gaskets OK or Replace		OK
2 1/2" Coupling		OK
3" Coupling		OK
Hub		OK

		Yes	No
A.	Hydrant Outlets are slightly more than hand tight	₩	
В.	Nozzle Threads are not damaged and lubricated	₩	
C.	Operation Nut shows signs of wear		✓
D.	Cracks visually appear in the Hydrant Barrel		✓
E.	There are leaks under caps due to worn gaskets		<b>√</b>
F.	There are leaks in the top of hydrant		✓
G.	Barrel drains satisfactory	✓	