

Button Name	Depress Code	Long Press Code	Release Code	CURRENT (AS-IS)			DESIRED (TO-BE)		
				Depress Action	Long Press Action	Quick Release Action	Depress Action	Long Press Action	Quick Release Action
Source	2e 20 02 07 01 d5	2e 20 02 07 02 d4	2e 20 02 07 00 d6	Launch radio	<none>	<none>	Launch radio	<none>	<none>
Volume Up	2e 20 02 01 01 db	2e 20 02 01 02 da	2e 20 02 01 00 dc	Volume Up	Volume Up	<none>	Volume Up	Volume Up	<none>
Volume Down	2e 20 02 02 01 da	2e 20 02 02 02 d9	2e 20 02 02 00 db	Volume Down	Volume Down	<none>	Volume Down	Volume Down	<none>
Left	2e 20 02 04 01 d8	2e 20 02 04 02 d7	2e 20 02 04 00 d9	Previous Track	<none>	<none>	Previous Track	<none>	<none>
Right	2e 20 02 03 01 d9	2e 20 02 03 02 d8	2e 20 02 03 00 da	Next Track	<none>	<none>	Next Track	<none>	<none>
Voice Assistant	2e 20 02 08 01 d4	2e 20 02 08 02 d3	2e 20 02 08 00 d5	<none>	Siri	Mute/Unmute toggle	<none>	<none>	Siri
Call Pick Up	2e 20 02 09 01 d3	2e 20 02 09 02 d2	2e 20 02 09 00 d4	Bluetooth/Carplay	<none>	<none>	<none>	Bluetooth/Carplay	Pick Up Call
Call end	2e 20 02 0a 01 d2	2e 20 02 0a 02 d1	2e 20 02 0a 00 d3	<none>	<none>	<none>	<none>	Mute/Unmute toggle	End Call

Confirmed that this APK does nothing to affect the button mapping shown above: <https://vhedia.tawkhel.com/article/mitsubishi-triton-mr-2018-2023-mic-swc-not-working>

Rather this is a model year 2023 Triton, when the post pandemic parts shortage was at its peak - suspect the above keycodes differ from earlier Triton MR years

Picture of buttons:



Confirmation CANBUS is set to 56, to get the level of button press functionality that is shown above:



Support for: Order #59960, placed on 23-March-2025