5/Feb/24 - Alarm Inputs

Need to work out power supply

ISOLATE

Used an up-converter 5V to 12V
for the inputs. Maybe charge
from this and close a relay
to feed batt to cpu if
POE fails?